Introduction to Electrical and Computer Engineering Design ECEG 201 Session 05 Lecture Notes

Announcements

- 1. In-class lab exercise on Friday. Bring your AD2.
- 2. First quiz on Monday, 2020-02-03. Covers homework through Homework 3.
- 3. To Hand In:
 - (a) Homework 3 is due on Friday, 2020-01-31

Temperature Sensors

- Record your sensor number on your worksheet.
- Do not lose or damage your sensor.

We do not have an unlimited supply of these sensors. If you damage or lose your sensor there will be a one-point deduction in your course grade for each replacement.

- Do not trust the AD2 supply. Use the voltmeter to **measure** the supply voltage.
- Record all of the digits from every measurement you make.